


# INSTRUCTION SHEET

ANLEITUNG • FEUILLE D'INSTRUCTIONS • HOJA DE INSTRUCCIONES

# CGR 3


Pyrgeometer



**KIPP & ZONEN**  
SINCE 1830

Kipp & Zonen B.V.  
P.O. Box 507, 2600 AM Delft  
The Netherlands  
T: +31 (0) 15 2755 210  
F: +31 (0) 15 2620 351  
info@kippzonnen.com  
www.kippzonnen.com

IP 67 CE



Keep original packaging for recalibration  
Verwahren Sie die Originalverpackung für den Versand zur Rekalibrierung  
Gardez l'emballage original pour le recalibrage  
Guarde el embalaje original para la recalibración

# USER INFORMATION • ANWENDERINFORMATION • INFORMATION UTILISATEUR • INFORMACIÓN PARA EL USUARIO

INFORMATION UTILISATEUR • INFORMACIÓN PARA EL USUARIO

## Read this document carefully before installation.

Warranty is 2 years from date of invoice, subject to correct installation and use. Kipp & Zonen accepts no liability for any loss or damages arising from incorrect use of the product. This device conforms to the EU 'CE' guideline 89/336/EEC 73/23/EEC. Unauthorised modifications may void the warranty and CE validity. For the latest product support information visit our website.

## Lesen Sie dieses Dokument sorgfältig vor der Installation

Die Garantie beträgt 2 Jahre ab dem Rechnungsdatum, abhängig von korrekter Installation und Gebrauch. Kipp & Zonen übernimmt keine Haftung für mögliche Verluste oder Beschädigungen, die durch den falschen Gebrauch des Produktes entstehen. Dieses Produkt entspricht der EU 'CE' Richtlinie 89/336/EEC 73/23/EEC. Nicht autorisierte Änderungen können die Garantie und die CE-Konformität aufheben. Die neuesten Produktinformationen finden Sie auf unserer Internetseite.

## Lisez ce document soigneusement avant installation

La garantie est de 2 ans à dater de la facture, pour une installation et une utilisation correctes. Kipp & Zonen n'accepte aucune responsabilité quant à la perte ou dommage résultant d'une utilisation incorrecte du produit. Ce dispositif est conforme à la directive EU "CE" 89/336/EEC 73/23/EEC. Toutes modifications non autorisées peuvent annuler la garantie et la validité CE. Consultez notre website pour tout renseignement "support produit".

## Lea este documento cuidadosamente antes de la instalación.

La garantía es de 2 años contados desde de la fecha de adquisición y está condicionada a una instalación y utilización correctas. Kipp & Zonen no acepta ninguna responsabilidad por pérdida o daños resultantes de un uso incorrecto del producto. Este dispositivo es conforme con las directrices 89/336/EEC 73/23/EEC de 'CE' y de la EU. Las modificaciones no autorizadas pueden anular la garantía y la validez CE. Para obtener la última de la información de soporte del producto les rogamos visiten nuestro website.

© 2010 Kipp & Zonen B.V.

## ALL RIGHTS RESERVED

ALLE RECHTE VORBEHALTEN  
TOUS DROITS RÉSERVÉS  
RESERVADOS TODOS LOS DERECHOS

## SPECIFICATIONS

SPECIFICATIONS • SPEZIFIKATIONEN • SPÉCIFICATIONS • ESPECIFICACIONES		
Spectral range	Ø 30 mm	4500 to 42000 nm
Height	68.3 mm	104.6 mm
Diameter	Ø 110 mm	Ø 12 mm L=300 mm
Ø 5.2 mm (2x)		
Ø 65 mm		
Ø 2x Ø 4x		
M5 x 30 (2x)		
M5 x 40 (2x)		
M5 x 50 (2x)		
Spectral range		
Response time	95 %	< 18 s
Non-linearity	-250 to 250 W/m²	< 1 %
Temperature dependence	-40 °C to +40 °C +40 °C to +80 °C	< 5 % < 10 %
Tilt error		< 2 %
Zero offset	dT = 5 K/h	< 5 W/m²
Non-stability (change/year)		< 1 %

## DELIVERY CONTENTS

LIEFERUMFANG • CONTENU DE LA LIVRAISON • CONTENIDO DEL SUMINISTRO

# MECHANICAL

MECHANISCHE • MECANIQUE • MECÁNICA

## ① Unobstructed horizon

Freier Horizont  
Horizon non obstrué  
Horizonte sin obstáculo

## ② Solid surface

Feste Oberfläche  
Surface solide  
Superficie sólida

## ③ Do not place near heat sources

Platzieren Sie den Sensor nicht in unmittelbarer Nähe von Wärmequellen  
Ne pas placer près des sources de chaleur  
No situar cerca de fuentes de calor

## ④ Point cable towards nearest pole

Kabelausrichtung zum nächsten Pol  
Pointez le câble vers le pôle le plus proche  
Oriental el cable hacia el polo más próximo

## ⑤ Level instrument

Nivellieren Sie den Sensor  
Instrument de niveau  
Nivelar el instrumento

## ⑥ Mount with screws, washers and nuts

Montage mit Schrauben, Muttern und Unterlegscheiben  
Montage avec les vis, anneaux et écrous  
Montaje con los tornillos, arandelas y tuercas

## ⑦ Mount sun screen

Montage des Sonnenschirms  
Montez l'écran solaire  
Montar de pantalla de sol

## ⑧ Net-radiation set-up

Nettostrahlungsmodus  
Installation du rayonnement net  
Ajuste de la radiación neta

# INSTALLATION

INSTALLATION • INSTALLATION • INSTALACION

Minimize interference from mounting device

Minimierung von Störungen durch die Montagevorrichtung  
Réduisez au minimum l'interférence du dispositif de support  
Mimízice las interferences del elemento de soporte

$h \approx 1.5 \text{ m above cut grass}$

$h = 1.5 \text{ m über kurz geschnittenem Gras}$

$h = 1.5 \text{ m au dessus de l'herbe rase}$

$h = 1.5 \text{ m sobre hierba segada}$

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

Diagram illustrating the installation height (h) relative to cut grass.

# ELECTRICAL

ELEKTRISCH • ÉLECTRIQUE • ELÉCTRICA

## PYRGEOMETER CONNECTION

ANSCHLUSS • RACCORDEMENT • CONEXIÓN

Wire	Function	Connect with
Kabel	Funktion	Anschluss an
Fil	Fonction	Relier à
Cable	Funció	Conectar con

1 Red	+	+ (Hi)
2 Blue	-	- (Lo)
Shield	Housing	Ground *

\* Connect to ground if radiometer not grounded  
Mit Erde verbinden, wenn das Radiometer nicht geerdet ist  
Reliez à la terre si le radiomètre n'est pas connecté  
Conectar a tierra si el radiómetro no lo está

## Thermistor (Standard • Standard • Etalon • Estándar)

Yellow	Gelb • Jaune • Amarillo	Thermistor
Green	Grün • Vert • Verde	

## Pt-100 (Optional • Option • Option • Opcional)

Yellow	Combined	Pt-100
Brown	Combined	
Green	Combined	
Grey	Combined	
	Grau • Gris • Gris	

Pin Layout (Instrument)  
Steckerbelegung • Schéma des connexions • Diagrama de conexiones

## Calculate Irradiance

Berechnung der Strahlung • Calcul de l'irradiance • Cálculo de la irradiancia

$$L_{d\downarrow} = L_{net} + 5.67 \cdot 10^{-8} \cdot T_b^4 \quad L_{net} = \frac{U_{emf}}{S}$$

$L_{d\downarrow}$  [W/m²] = Downward Longwave Radiation  
Nach unten gerichtete langwellige Strahlung  
Rayonnement descendant longue onde  
Radiación de onda larga hacia abajo

$L_{net}$  [W/m²] = Net Radiation  
Nettostrahlung • Rayonnement net • Radiación neta

$U_{emf}$  [ $\mu$ V] = Output Voltage  
Ausgangsspannung • Sortie tension • Voltaje de salida

$S$  [ $\mu$ V/W/m²] = Sensitivity  
Empfindlichkeit • Sensibilité • Sensibilidad

$T_b$  [K] = Temperature  
Temperatur • Température • Temperatura

## Calculate temperature

Temperaturberechnung • Calcul de la température • Cálculo de la temperatura

$$Pt-100 (100 \Omega @ 0^\circ\text{C}) \quad Thermistor (10 k\Omega @ 25^\circ\text{C})$$

$$T = \frac{-\alpha + \sqrt{\alpha^2 - 4 \cdot \beta \cdot \left( \frac{-R}{100} + 1 \right)}}{2 \cdot \beta} \quad T = \left( \alpha + [\beta \cdot (\ln(R)) + \gamma \cdot (\ln(R))^2] \right)^{-1} - 273.15$$

$\alpha$ : 3.9080  $\cdot 10^{-3}$     $\beta$ : -5.8019  $\cdot 10^{-7}$     $\gamma$ : 1.568  $\cdot 10^{-7}$

$T$  [°C] = Temperature  
Temperatur • Température • Temperatura

$R$  [Ω] = Resistance  
Widerstand • Résistance • Resistencia

## Temperature unit conversion

Temperaturreinheit Umwandlung • Conversion d'unité de la température • Conversión de la unidad de la temperatura

$$[K] = [^\circ\text{C}] + 273.15$$